

Cisco Systems Inc

125 West Tasman Drive San Jose, CA 95134-1706
Tel: 408-853-5965 / Fax: 408-853-5965

Restricted band Declaration Letter

Date: 2015/2/4

FCC ID : LDKASA-AP702

We, the undersigned, attest that this device does not support operation in the 5600 - 5650 MHz Band. The firmware on the device restricts the operation in this frequency band and does not utilize the channels in this band.

FCC Grantee contact person information.

Applicant's company name : Cisco Systems Inc

Applicant's company address : 125 West Tasman Drive San Jose, CA 95134-1706

Signature :

A handwritten signature in black ink, appearing to read 'Don Foster', is written over a horizontal line. The signature is enclosed within a large, hand-drawn oval.

Name and Job Title : Don Foster GDS compliance

E-Mail : dofoster@cisco.com

Tel. : 408-853-5965