



# GIANT ELECTRONICS LTD.

MODEL: T8260D

TITLE: UNIT PACKING

REV.	PRE.BY	DATE	CHK.BY	DATE	APP.BY	DATE
A	KELLY ZHU	24/FEB/05	BIRD CHENG	24/FEB/05	ZEUS CHAN	24/FEB/05



## NOTES:


1. STICK THE LENS PROTECT PAPER TO THE LCD LENS.
2. STICK THE FCC LABEL & SN LABEL INTO BATTERY BOX.

# GIANT ELECTRONICS LTD.

MODEL: T8260D

TITLE: SN LABEL FORMAT

REV.	PRE.BY	DATE	CHK.BY	DATE	APP.BY	DATE
A	KELLY ZHU	24/FEB/05	BIRD CHENG	24/FEB/05	ZEUS CHAN	24/FEB/05



unit: mm

## THE FORMAT OF THE SERIAL NUMBER:

Serien-Nr.

GMMY99999

G=Alpha character Factory code  
(G=Giant)

MONTH OF MANUFACTURE (MM)

IDENTIFIED BY TWO DIGITS

JANUARY 01  
FEBRUARY 02  
TO  
DECEMBER 12

YEAR OF MANUFACTURE (YY)

IDENTIFIED BY ONE ALPHA CHAR.

2004 B  
2005 C  
2006 D  
I  
AND SO ON

G MM Y 99999

G=ALPHA CHARACTER FACTORY CODE  
MM=TWO-DIGIT NUMBER FOR MONTH OF MANUFACTURE  
Y=ALPHA CHARACTER FOR YEAR OF MANUFACTURE  
99999=FIVE DIGIT SEQUENTIAL SERIAL NUMBER  
STARTING FROM '00001' AND REFER TO UNIT NUMBER  
OF REQUIREMENT MARKED ON PO.

## NOTES:

1.MATERIAL:BLANK LABEL:KEM-PK7183

FACESTOCK: 2.0MIL GLOSS WHITE CAST VINYL NONTOPCOATED

ADHESIVE: 0.8MIL #350 HIGH-HODDING ACRYLIC ADHESIVE

LINER: 3.2MIL 55# WHITE CENSIFIED KRAFT PAPER, SILICONE COATED

2.PLEASE PROVIDE THE BLANK LABE IN ROLL FORM.

3.THE MATERIALMUST PASS TEST AS THEA'S SPECIFICATION  
REQUEST. THE DETAIL AS FOLLOWS:

A>THE RUBBING TEST: INCLUDE USE THE WATER AND PETROLEUM.


B>THE HIGH AND LOW TEMPERATURE TEST.

C>THE HUMIDITY TEST.

4.PRINTING COLOR: BLACK.

# GIANT ELECTRONICS LTD.

MODEL: T8260D			TITLE: FCC LABEL FORMAT			
REV.	PRE.BY	DATE	CHK.BY	DATE	APP.BY	DATE
A	KELLY ZHU	24/FEB/05	BIRD CHENG	24/FEB/05	ZEUS CHAN	24/FEB/05



unit: mm

- NOTES:
- 1.MATERIAL:BLANK LABEL:KEM-PK7183  
FACESTOCK: 2.0MIL GLOSS WHITE CAST VINYL NONTOPCOATED  
ADHESIVE: 0.8MIL #350 HIGH-HODDING ACRYLIC ADHESIVE  
LINER: 3.2MIL 55# WHITE CENSIFIED KRAFT PAPER, SILICONE COATED
  - 2.PLEASE PROVIDE THE BLANK LABLE IN ROLL FORM.
  - 3.THE MATERIALMUST PASS TEST AS THEA'S SPECIFICATION REQUEST. THE DETAIL AS FOLLOWS:
    - A>THE RUBBING TEST: INCLUDE USE THE WATER AND PETROLEUM.
    - B>THE HIGH AND LOW TEMPERATURE TEST.
    - C>THE HUMIDITY TEST.
  - 4.PRINTING COLOR: BLACK.