



Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 12:41:36

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 12.MAR.2022 12:42:05

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:04:00

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:04:29

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:06:26

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:06:49

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:07:22

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:07:44

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:08:14

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:08:39

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:09:09

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:09:31

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:10:05

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:10:30

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)





Date: 12.MAR.2022 13:10:59


Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)



Date: 12.MAR.2022 13:11:22




Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:12:42

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:13:04

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:13:38

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:14:03

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:14:37

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:14:59

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:15:30

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:15:49

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:16:16

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:16:35

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:17:07

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:17:30

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:18:07

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:18:29

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:19:08

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:19:30

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:20:00

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:20:22

Band 4_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:20:53

Band 4_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:21:15

Band 4_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:21:41

Band 4_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:22:04

Band 4_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:22:30

Band 4_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:22:52

Band 4_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:23:20

Band 4_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:23:45

Band 4_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:24:21

Band 4_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:24:50

Band 4_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:25:22

Band 4_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:25:47

Band 4_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:26:15

Band 4_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:26:41

Band 4_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:27:13

Band 4_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:27:35

Band 4_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:28:01

Band 4_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:28:21

Band 4_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:29:02

Band 4_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:29:21

Band 4_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:29:51

Band 4_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 12.MAR.2022 13:30:20

Band 4_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)



Date: 12.MAR.2022 13:30:53

Band 4_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)



Date: 12.MAR.2022 13:31:16