


Page 1 of 28 Report No.: LGT22I066

Appendix - Internal Photographs of EUT Constructional Details

FCC ID: 2AQ7Q-DBR1455 Model: DBR1455 Photo 1



Photo 2





Page 2 of 28 Report No.: LGT22I066

Photo 3




Photo 4






Photo 5




Photo 6






Photo 7




Photo 8





Photo 9




Photo 10






Photo 11




Photo 12 TP control board type A






Photo 13 TP control board type A





Photo 14 TP control board type A





Page 8 of 28 Report No.: LGT22I066

Photo 15 TP control board type B






Photo 16 TP control board type B






Page 9 of 28 Report No.: LGT22I066









Page 10 of 28 Report No.: LGT22I066






Photo 20 TP Board type A






Photo 21 TP Board type A




Photo 22 TP Board type A






Photo 23 TP Board type B




Photo 24 TP Board type B











Photo TP Board type C






AV Bar

Photo 27



Photo 28





Page 15 of 28 Report No.: LGT22I066

Photo 29




Photo 30

