

28th July 2005

NOKIA CORPORATION
Nokia Mobile Phones
Frederikskaj
Sydhavnsgade 15-19
DK-1790 Copenhagen V
Denmark
Tel +45 3329 2929
Fax +45 3329 2001

28th July 2005

IT030A IT030G part code change on VCO from FDK

The part code on the VCO from FDK has changed from IT030A to IT030G. The main VCO design, specification, performance and package are the same for the two codes IT030A IT030G.

The transmitter output power is aligned according to the tuning procedure as presented in the original FCC application. The radiated and conducted power would not be affected by this type of change.