
Issued: 05/10/2023 Revised: 10/10/203


6.5 Setup Photograph:



Issued: 05/10/2023 Revised: 10/10/203

7.5 Setup Photographs:






Issued: 05/10/2023 Revised: 10/10/203

8.5 Setup Photograph:




Issued: 05/10/2023 Revised: 10/10/203


9.5 Setup Photographs:





Issued: 05/10/2023 Revised: 10/10/203






Issued: 05/10/2023 Revised: 10/10/203

Short Side





Report Number: 105128961BOX-001.2 Issued: 05/10/2023

Revised: 10/10/203

10.4 Setup Photographs:




Non-Specific Radio Report Shell Rev. October 2022 Client: Otodata Wireless Network, Inc. / Model: C033

Page 36 of 87


Issued: 05/10/2023 Revised: 10/10/203

Radiated Emission Test Setup (Back Side), 30-1000 MHz







Issued: 05/10/2023 Revised: 10/10/203






Issued: 05/10/2023 Revised: 10/10/203





Issued: 05/10/2023 Revised: 10/10/203






Issued: 05/10/2023 Revised: 10/10/203








Issued: 05/10/2023 Revised: 10/10/203

Radiated Emission Test Setup (Short Side), 1-13 GHz






Report Number: 105128961BOX-001.2 Issued: 05/10/2023 Revised: 10/10/203

Radiated Emission Testing Setup, 13-18 GHz

Report Number: 105128961BOX-001.2 Issued: 05/10/2023 Revised: 10/10/203


Radiated Emission Manual Testing Setup, 18-25 GHz



Report Number: 105128961BOX-001.2 Issued: 05/10/2023 Revised: 10/10/203

11.5 Setup Photographs:





Issued: 05/10/2023 Revised: 10/10/203

1-13 GHz Test Setup



