



Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:48:50

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:49:09

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:49:38

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:50:04

Band 12_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:50:30

Band 12_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:50:59

Band 12_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:51:24

Band 12_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:51:52

Band 12_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:52:15

Band 12_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:52:38

Band 12_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:53:07

Band 12_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:53:36

Band 12_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:54:03

Band 12_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:54:29

Band 12_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:54:58

Band 12_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:55:24

Band 12_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:55:56

Band 12_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:56:22

Band 12_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:56:56

Band 12_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:57:22

Band 12_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:57:56

Band 12_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:58:24

Band 12_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:58:52

Band 12_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.MAR.2022 13:59:11

Band 17_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 13:59:41

Band 17_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.MAR.2022 14:00:04

Band 17_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 14:00:33

Band 17_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.MAR.2022 14:00:56

Band 17_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 14:01:25

Band 17_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 12.MAR.2022 14:01:50

Band 17_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 14:02:19

Band 17_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.MAR.2022 14:02:45

Band 17_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 14:03:18

Band 17_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.MAR.2022 14:03:44

Band 17_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 14:04:17

Band 17_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 12.MAR.2022 14:04:43

Band 38_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 15:05:45

Band 38_5 MHz_Low_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:06:14

Band 38_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 15:06:47

Band 38_5 MHz_Middle_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:07:12

Band 38_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 12.MAR.2022 15:07:35

Band 38_5 MHz_High_QPSK_RB25#0_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:07:58

Band 38_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 15:08:29

Band 38_10 MHz_Low_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:08:58

Band 38_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 15:09:25

Band 38_10 MHz_Middle_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:09:51

Band 38_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 12.MAR.2022 15:10:24

Band 38_10 MHz_High_QPSK_RB50#0_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:10:47

Band 38_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.MAR.2022 15:11:18

Band 38_15 MHz_Low_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:11:47

Band 38_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.MAR.2022 15:12:16

Band 38_15 MHz_Middle_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:12:45

Band 38_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 12.MAR.2022 15:13:21

Band 38_15 MHz_High_QPSK_RB75#0_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:13:40

Band 38_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.MAR.2022 15:14:14

Band 38_20 MHz_Low_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:14:39

Band 38_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 12.MAR.2022 15:15:15

Band 38_20 MHz_Middle_QPSK_RB100#0_2(1GHz-26.5GHz)




Date: 12.MAR.2022 15:15:41

Band 38_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)



Date: 12.MAR.2022 15:16:10

Band 38_20 MHz_High_QPSK_RB100#0_2(1GHz-26.5GHz)



Date: 12.MAR.2022 15:16:36