



Plot on Configuration VHT20 / 5500 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 31.MAR.2018 22:31:32

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 31.MAR.2018 22:38:35

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 3 / 3GHz~6GHz



Date: 31.MAR.2018 22:45:59

Plot on Configuration VHT20 / 5500 MHz / Peak / Port 4 / 3GHz~6GHz



Date: 31.MAR.2018 22:57:17

Plot on Configuration VHT20 / 5580 MHz / Average / Port 1 / 3GHz~6GHz




Date: 31.MAR.2018 23:06:14

Plot on Configuration VHT20 / 5580 MHz / Average / Port 2 / 3GHz~6GHz



Date: 31.MAR.2018 23:18:07

Plot on Configuration VHT20 / 5580 MHz / Average / Port 3 / 3GHz~6GHz




Date: 31.MAR.2018 23:24:45

Plot on Configuration VHT20 / 5580 MHz / Average / Port 4 / 3GHz~6GHz




Date: 31.MAR.2018 23:34:04

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 31.MAR.2018 23:09:22

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 31.MAR.2018 23:18:44

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 3 / 3GHz~6GHz



Date: 31.MAR.2018 23:25:36

Plot on Configuration VHT20 / 5580 MHz / Peak / Port 4 / 3GHz~6GHz



Date: 31.MAR.2018 23:34:59

Plot on Configuration VHT20 / 5700 MHz / Average / Port 1 / 3GHz~6GHz




Date: 31.MAR.2018 23:41:43

Plot on Configuration VHT20 / 5700 MHz / Average / Port 2 / 3GHz~6GHz



Date: 31.MAR.2018 23:47:53

Plot on Configuration VHT20 / 5700 MHz / Average / Port 3 / 3GHz~6GHz




Date: 31.MAR.2018 23:54:11

Plot on Configuration VHT20 / 5700 MHz / Average / Port 4 / 3GHz~6GHz




Date: 1.APR.2018 00:00:26

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 31.MAR.2018 23:42:22

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 31.MAR.2018 23:48:44

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 3 / 3GHz~6GHz



Date: 31.MAR.2018 23:55:09

Plot on Configuration VHT20 / 5700 MHz / Peak / Port 4 / 3GHz~6GHz



Date: 1.APR.2018 00:01:25

Plot on Configuration VHT20 / 5720 MHz / Average / Port 1 / 3GHz~6GHz



Date: 1.APR.2018 00:08:40

Plot on Configuration VHT20 / 5720 MHz / Average / Port 2 / 3GHz~6GHz



Date: 1.APR.2018 00:16:11

Plot on Configuration VHT20 / 5720 MHz / Average / Port 3 / 3GHz~6GHz




Date: 1.APR.2018 00:23:01

Plot on Configuration VHT20 / 5720 MHz / Average / Port 4 / 3GHz~6GHz




Date: 1.APR.2018 00:29:37

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 1.APR.2018 00:09:32

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 1.APR.2018 00:17:00

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 3 / 3GHz~6GHz



Date: 1.APR.2018 00:23:37

Plot on Configuration VHT20 / 5720 MHz / Peak / Port 4 / 3GHz~6GHz



Date: 1.APR.2018 00:30:27

Plot on Configuration VHT40 / 5510 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.APR.2018 01:48:35

Plot on Configuration VHT40 / 5510 MHz / Average / Port 2 / 3GHz~6GHz



Date: 3.APR.2018 01:55:15

Plot on Configuration VHT40 / 5510 MHz / Average / Port 3 / 3GHz~6GHz




Date: 3.APR.2018 02:00:47

Plot on Configuration VHT40 / 5510 MHz / Average / Port 4 / 3GHz~6GHz




Date: 3.APR.2018 02:13:36

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 3.APR.2018 01:49:28

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.APR.2018 01:55:56

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 3 / 3GHz~6GHz




Date: 3.APR.2018 02:01:28

Plot on Configuration VHT40 / 5510 MHz / Peak / Port 4 / 3GHz~6GHz



Date: 3.APR.2018 02:16:54

Plot on Configuration VHT40 / 5550 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.APR.2018 02:28:38

Plot on Configuration VHT40 / 5550 MHz / Average / Port 2 / 3GHz~6GHz



Date: 3.APR.2018 02:36:16

Plot on Configuration VHT40 / 5550 MHz / Average / Port 3 / 3GHz~6GHz




Date: 3.APR.2018 02:41:43

Plot on Configuration VHT40 / 5550 MHz / Average / Port 4 / 3GHz~6GHz




Date: 3.APR.2018 02:52:26

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 3.APR.2018 02:30:25

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.APR.2018 02:36:57

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 3 / 3GHz~6GHz



Date: 3.APR.2018 02:42:18

Plot on Configuration VHT40 / 5550 MHz / Peak / Port 4 / 3GHz~6GHz



Date: 3.APR.2018 02:53:19

Plot on Configuration VHT40 / 5670 MHz / Average / Port 1 / 3GHz~6GHz




Date: 3.APR.2018 20:12:29

Plot on Configuration VHT40 / 5670 MHz / Average / Port 2 / 3GHz~6GHz



Date: 3.APR.2018 20:24:29

Plot on Configuration VHT40 / 5670 MHz / Average / Port 3 / 3GHz~6GHz




Date: 3.APR.2018 20:35:00

Plot on Configuration VHT40 / 5670 MHz / Average / Port 4 / 3GHz~6GHz




Date: 3.APR.2018 20:47:59

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 3.APR.2018 20:14:03

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.APR.2018 20:25:58

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 3 / 3GHz~6GHz



Date: 3.APR.2018 20:36:01

Plot on Configuration VHT40 / 5670 MHz / Peak / Port 4 / 3GHz~6GHz



Date: 3.APR.2018 20:48:56

Plot on Configuration VHT40 / 5710 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.APR.2018 20:57:18

Plot on Configuration VHT40 / 5710 MHz / Average / Port 2 / 3GHz~6GHz



Date: 3.APR.2018 21:06:12

Plot on Configuration VHT40 / 5710 MHz / Average / Port 3 / 3GHz~6GHz




Date: 3.APR.2018 21:19:55

Plot on Configuration VHT40 / 5710 MHz / Average / Port 4 / 3GHz~6GHz




Date: 3.APR.2018 21:28:39

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 3.APR.2018 20:58:44

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.APR.2018 21:07:30

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 3 / 3GHz~6GHz




Date: 3.APR.2018 21:20:53

Plot on Configuration VHT40 / 5710 MHz / Peak / Port 4 / 3GHz~6GHz




Date: 3.APR.2018 21:29:37

Plot on Configuration VHT80 / 5530 MHz / Average / Port 1 / 3GHz~6GHz




Date: 3.APR.2018 21:45:56

Plot on Configuration VHT80 / 5530 MHz / Average / Port 2 / 3GHz~6GHz




Date: 3.APR.2018 22:00:15

Plot on Configuration VHT80 / 5530 MHz / Average / Port 3 / 3GHz~6GHz




Date: 3.APR.2018 22:08:22

Plot on Configuration VHT80 / 5530 MHz / Average / Port 4 / 3GHz~6GHz




Date: 3.APR.2018 22:17:13

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 3 APR 2018 21:47:44

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3 APR 2018 22:01:14

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 3 / 3GHz~6GHz



Date: 3.APR.2018 22:09:38

Plot on Configuration VHT80 / 5530 MHz / Peak / Port 4 / 3GHz~6GHz



Date: 3.APR.2018 22:18:18

Plot on Configuration VHT80 / 5610 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.APR.2018 22:29:08

Plot on Configuration VHT80 / 5610 MHz / Average / Port 2 / 3GHz~6GHz



Date: 3.APR.2018 22:40:12

Plot on Configuration VHT80 / 5610 MHz / Average / Port 3 / 3GHz~6GHz




Date: 3.APR.2018 22:48:10

Plot on Configuration VHT80 / 5610 MHz / Average / Port 4 / 3GHz~6GHz




Date: 3.APR.2018 22:59:03

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 3.APR.2018 22:30:09

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.APR.2018 22:41:14

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 3 / 3GHz~6GHz



Date: 3.APR.2018 22:49:01

Plot on Configuration VHT80 / 5610 MHz / Peak / Port 4 / 3GHz~6GHz



Date: 3.APR.2018 22:59:56

Plot on Configuration VHT80 / 5690 MHz / Average / Port 1 / 3GHz~6GHz



Date: 3.APR.2018 23:35:33

Plot on Configuration VHT80 / 5690 MHz / Average / Port 2 / 3GHz~6GHz



Date: 3.APR.2018 23:15:46

Plot on Configuration VHT80 / 5690 MHz / Average / Port 3 / 3GHz~6GHz




Date: 3.APR.2018 23:21:52

Plot on Configuration VHT80 / 5690 MHz / Average / Port 4 / 3GHz~6GHz




Date: 3.APR.2018 23:37:18

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 1 / 3GHz~6GHz




Date: 3.APR.2018 23:10:38

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 2 / 3GHz~6GHz




Date: 3.APR.2018 23:16:34

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 3 / 3GHz~6GHz




Date: 3.APR.2018 23:22:34

Plot on Configuration VHT80 / 5690 MHz / Peak / Port 4 / 3GHz~6GHz




Date: 3.APR.2018 23:38:07

Plot on Configuration VHT20 / 5260 MHz / Average / Port 1 / 6GHz~9GHz




Date: 4 APR. 2018 00:02:15

Plot on Configuration VHT20 / 5260 MHz / Average / Port 2 / 6GHz~9GHz




Date: 4 APR. 2018 00:33:12

Plot on Configuration VHT20 / 5260 MHz / Average / Port 3 / 6GHz~9GHz




Date: 4.APR.2018 00:47:20

Plot on Configuration VHT20 / 5260 MHz / Average / Port 4 / 6GHz~9GHz




Date: 4.APR.2018 00:50:02

Plot on Configuration VHT20 / 5260 MHz / Peak / Port 1 / 6GHz~9GHz




Date: 4.APR.2018 00:03:05

Plot on Configuration VHT20 / 5260 MHz / Peak / Port 2 / 6GHz~9GHz




Date: 4.APR.2018 00:33:56

Plot on Configuration VHT20 / 5260 MHz / Peak / Port 3 / 6GHz~9GHz




Date: 4 APR, 2018 00:48:05

Plot on Configuration VHT20 / 5260 MHz / Peak / Port 4 / 6GHz~9GHz




Date: 4 APR, 2018 00:50:44

Plot on Configuration VHT20 / 5300 MHz / Average / Port 1 / 6GHz~9GHz




Date: 4 APR. 2018 01:01:21

Plot on Configuration VHT20 / 5300 MHz / Average / Port 2 / 6GHz~9GHz




Date: 4 APR. 2018 01:04:00

Plot on Configuration VHT20 / 5300 MHz / Average / Port 3 / 6GHz~9GHz



Date: 4 APR 2018 01:18:20

Plot on Configuration VHT20 / 5300 MHz / Average / Port 4 / 6GHz~9GHz



Date: 4 APR 2018 01:20:41