



3390 East Harmony Road
Fort Collins
Colorado 80528
United States

Date: December 30, 2021

Federal Communications Commission
Office of Engineering and Technology Laboratory Division
7435 Oakland Mills Rd
Columbia MD 21046-1609

To whom it may concern,

This Change of Identification request applies for a new FCC ID as established in 47CFR 2.933(b) for a currently approved device. This application by **HP Inc.** will establish a new FCC ID: **B94-RTL8852BER** under **HP Inc.** grantee code for purpose of marketing. The original grant to **Realtek Semiconductor Corp.** will remain in effect.

Per 2.933(b)

1. The original identification is **TX2-RTL8852BE**.
2. The original grant date is **08/13/2021**
3. The equipment is electrically identical. Only the trade name and FCC ID number are different.
4. The original test results are applicable and representative of this changed device.

The following files are electronically submitted as attachments:

- ♦ Cover Letter
- ♦ External Photos
- ♦ FCC ID label format and location

Sincerely yours,



Liang Rong Chiao

Worldwide Technical Regulations
HP International Pte. Ltd., Taiwan Branch
10F-1, 66, Jingmao 2nd Road, Nangang District, Taipei 115. Taiwan
frances.liang@hp.com
T +886-2-37892469