



American Telecommunications Certification Body Inc.  
6731 Whittier Ave, McLean, VA 22101

September 10, 2006

RE: Airspan Networks (Israel) Ltd.

FCC ID: PIDASMAX58

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) Please provide a view of the back side of the digital interface motherboard.
- 2) The label appears to use language from 15.19(a)(1). However given this is an unlicensed device, the labeling should be for 15.19(a)(3). Please review/correct.
- 3) The external/internal photographs appear to support an external antenna, but this does not appear to be addressed in the application nor does the device appear to be designed internally for such a connection. Please review/correct/clarify/explain as necessary.

Note: Users manual suggests some models with Antenna Connector, however this device does not appear to provide this. Please review.

- 4) Regarding the RF exposure, please calculate the power density at 20 cm. FCC no longer desires to see a safe distance < 20 cm (otherwise is is considered as portable and would required SAR testing). Please adjust.
- 5) Schematics appears to show 2 antenna connections, but from internal photographs this does not even appear to be a possibility. Please review schematic and confirm if correct schematics have been provided.
- 6) The users manual does not appear to address user to antenna RF exposure conditions (distances). Please update.

Timothy R. Johnson  
Examining Engineer

[mailto: tjohnson@AmericanTCB.com](mailto:tjohnson@AmericanTCB.com)

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.