

Company: Wallys Communications Technologies Co.,Ltd
Add: Room 2723, Le Jia building, Jia Rui Xiang No.8, Suzhou Industrial Park,
Suzhou, P.R 215000 China
Tel: +86-18912606205
Fax: +86-512-62815802
E-mail: jason@wallystech.com

Date: 2020-02-17
FEDERAL COMMUNICATIONS
COMMISSIONS Authorization and Evaluation
Division 7435 Oakland Mills Road
Columbia, MD 21046

Attestation Letter

To Whom It May Concern,

The chip IPQ4029 installed in our product Wireless Router Module (model name: DR4029 , Series Model:DR4019,FCC ID: 2AG7VDR4029), which are supports 2.4G Wi-Fi(802.11b/802.11g/ 802.11n-HT20/ 802.11n-HT40) and 5G Wi-Fi(5150~5250MHz, 5250~5350MHz , 5470~5725MHz,5725~5850MHz) fuctions, But for the product, it only activates the 2.4G Wi-Fi(802.11b/802.11g/802.11n-HT20/ 802.11n-HT40) and 5G Wi-Fi(5150~5250MHz, 5725~5850MHz) fuction, the 5G Wi-Fi(5250-5350MHz , 5470-5725MHz) fuction was disabled by using the software.

Please contact me if there is need for any additional clarification or information.

Best Regards,

Sincerely,

Signature: 

Typed or Printed Name: Jason Sun

Title: CEO