



Askey Computer Corporation
10F, No. 119, Jiankang Rd., Zhonghe Dist.,
New Taipei City, 23585, Taiwan

Date: 2024-07-09

Re: Supersede request for FCC ID: H8NEAO2522P-2; Granted on 07/05/2024

To Whom It May Concern:

We regret to inform you that due to **type the wrong Model No. on test reports, EUT photos and Operational Description**, we have submitted the wrong **Test reports, EUT photos and Operational Description** exhibit to the filing.

To prevent misunderstanding to the public, we would like to request the FCC to supersede the exhibit described below:

Original	New	Change
Test Report (DSS)	Test Report (DSS)_rev	Modified the Model no. to EAO2522P-2-FCC
Test Report (DFS)_rev	Test Report (DFS)_rev 2	
Test Report (DTS-BT LE)	Test Report (DTS-BT LE)_rev	
Test Report (DTS-WLAN)_rev	Test Report (DTS-WLAN)_rev 2	
Test Report (NII)_rev 2	Test Report (NII)_rev 3	
RF Exposure Info (MPE)_rev 2	RF Exposure Info (MPE)_rev 3	
Operational Description_rev 2	Operational Description_rev 3	
External Photos	External Photos_rev	
Internal Photos_rev 2	Internal Photos_rev 3	

If you have any questions, feel free to contact us. Thank you.

Regards,



Jack Po, Manager
Askey Computer Corp
Tel: 886 2 2228-7588 #18734
Fax: 886 2 3234-9340
E-mail: jackpo@askey.com