Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 Direct: 408 526 4000 FAX: 408 526 4100 www.cisco.com

Declaration of changes from	9553/9540	to Variant

General: Cisco cp-860s/cp-860\_ is a variant product of Spectralink 9553/9540

## SOFTWARE MODIFICATIONS:

Protocol Stack changes: NO

MMS/STK/USAT/USIM changes: no

> DM/SUPL/VT/FUMO/SWP/HCI: no

Other changes detailed:

Brand name/Manufacture/Model name

OS upgrade from Android 8.1 to Android 10.0, the SW version will change to 1.0.0.8E. the HW version will change to H. Battery keep use the same one, but the manufacture name will change to Cisco/Model Name will change to CP-860-BAT.

## HARDWARE MODIFICATIONS:

Baseband changes: no

Band changes: no

Antenna changes: no
PCB Layout changes: no
Main components changes: no

	Antanna	AP	MODEM	Transceiver	Balun	Band pass filter	diplexer
Bluetooth							
wifi							

> Bluetooth changes: no

> WiFi changes: no

FM changes:

NFC changes: no

Other components changes: no TP/LCD/ Camera changes: no

Other changes detailed: no

## • MECHANICAL MODIFICATIONS:

Use new metal front/back cover or keypad: No change

Mechanical shell changes: no

Whole size of EUT: NO

Distance of Ear reference point to bottom of handset: no

Other trinkets to change the surface of handset: Other changes detailed: no

2 /-

**APPROVED BY:** 

Emily Jaser Compliance Program Manager

Signature: Date: 20201207