May. 09, 2025

--- Covered List Software Incapability 1 ---

		DT004 DT000 DT000	TE004 TE000 TE000						
	Device (model name):	BT001, BT002, BT003, TE001, TE002, TE003							
	Grantee:	Shenzhen Heearly Technology Co.,Ltd.							
	FCC ID:	2BO5D-BT001							
Device featu	res:								
Operating System (as applicable):		N/A							
Storage Capacity (hard drive or other permanent memory storage):		N/A							
software po		☐ YES	⊠ NO						
Does the de connection?	vice have an internet ?	⊠ YES	□NO						
Can the dev	ice connect to a PC?	⊠ YES	□NO						
Chipset/module information:									
Chipset / module part number:		Memory size (MB)							
TXW816		N/A							
Minimum system requirements Kaspersky as of December 3, 2024									
Android	Memory: 120 MB	Disc space: unknown Proc	nknown Processor speed: unknown						
MacOS Windows	Memory: 2000 MB Memory: 1000 MB	•	Processor speed: unknown Processor speed: 1 GHz						
Linux	Memory: 1000 MB	Disc space: 1000 MHz Proc	Processor speed: 1 GHz						
Based on the review of the above factsheet(s) and device features, the device									
□ cannot support installation of any cybersecurity or anti-virus software on the covered list.									
potentially can operate with any cybersecurity or anti-virus software on the covered list –									
additional 3 rd party proof is provided to demonstrate compliance with requirements as of									
2.911(d)5(i),(ii) – page 2 of this document applies.									
Signature:									
	Signature.	clare Wen							
	Name:	Clare Wen							
	Title/Position:	Manager							
1									

Note: If the device is capable of running Kaspersky software, at least one document must be provided from a third party showing that the Kaspersky software is not present on the device. This could include the results of a software scan, a screen capture of the device software register or other objective evidence that proves the Kaspersky software is not on the device. Please follow options listed on page 2.

¹ List of minimum requirements to implement covered list software – if the EUT does not have capability to install Kaspersky under the given configuration. Page 2 must also be handed in.

63_Compliance proof covered list- 2.911(d)(5)(i) and (ii)-software_V02

Shenzhen Heearly Technology Co.,Ltd.

- Options to provide of compliance with covered list software requirements -

Please t	fill in as applicable and provide additional proof as req	ues	sted:				
1	Has the client signed an attestation stating the device is incapable of running the Kaspersky software (page 1)?	\boxtimes	YES*		NO**		
	* YES – no more proof needed – 2-5 do not apply > N/A						
	** NO – more proof must be provided (item 2-5 must be						
	answered)						
_	-	_	L	_			
2	Did the test lab or other 3rd party other than the certification body and applicant provide a list of software installed on the device and is there no evidence of Kaspersky software being installed?		YES***		NO	\boxtimes	N/A
	***YES – please:						
	Insert File Name:						
	Insert 3 rd Party Name:						
3	Have the results of a software scan been provided showing that Kaspersky software is not installed on the device?		YES***		NO		N/A
	***YES – please:						
	Insert File Name:						
	Insert 3 rd Party Name:						
	moon of any name.						
4	Has any other objective evidence that Kaspersky software is not installed on the device been provided?		YES***		NO	\boxtimes	N/A
	***YES – please:						
	Insert File Name:						
	Insert 3rd Party Name:						
	Insert 3° Faity Name.						
Г		_	L	_			
5	Has at least one of the above items been shown as a YES?		YES		NO****		
	**** NO – applicant failed to provide sufficient proof –						
	application filing is rejected.						

Note:

Files containing confidential operational details can be kept long-term confidential on applicant's request.