

FCC TEST REPORT Report No.: FG492412

Appendix C. Set up Photograph

Spurious Radiation



FRONT VIEW



REAR VIEW

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C1 of C2 Issued Date : Oct. 04, 2004 FCC TEST REPORT Report No.: FG492412



Frequency Stability

SPORTON International Inc.

TEL: 886-2-2696-2468 FAX: 886-2-2696-2255 Page No. : C2 of C2 Issued Date : Oct. 04, 2004