

American Telecommunications Certification Body Inc. 6731 Whittier Ave, McLean, VA 22101

July 25, 2002

RE: Martec Access Products, Inc.

FCC ID: JCQ993

After a review of the submitted information, I have a few comments on the above referenced Application.

- 1) FYI, The label frequency appears as ".303". This may or may not be intentional.
- 2) The test report states on page 4 "the transmitter was activated using the lock/unlock button, with a special wooden clamp...". Please explain as this product does not appear to be activated in this manner.
- 3) Please show compliance with the device shutting off in < 5 seconds after the alarm condition is over (vibration has stopped).

Timothy R. Johnson Examining Engineer

mailto: tjohnson@AmericanTCB.com

The items indicated above must be submitted before processing can continue on the above referenced application. Failure to provide the requested information may result in application termination. Correspondence should be considered part of the permanent submission and may be viewed from the Internet after a Grant of Equipment Authorization is issued.

Please do not respond to this correspondence using the email reply button. In order for your response to be processed expeditiously, you must submit your documents through the AmericanTCB.com website. Also, please note that partial responses increase processing time and should not be submitted.

Any questions about the content of this correspondence should be directed to the sender.