



Continental Automotive Systems Corporation

45-29, Saeum-ro, Icheon-si, Gyeonggi-Do, Korea
T. 82-31-645-4864, F. 82-31-637-0371

Date: September 17, 2020

To: MiCOM Labs
575 Boulder Court, Pleasanton,
California 94566, United States

Model: SVI-MQ4FGE03

FCC ID: SY5MQ4FGE03

Dear Sir/Madam,

Label is placed in the battery compartment due to below reason:

The label placed on the exterior of the equipment affect the appearance according to design requirements because it would be easily removed and limited space of label area.

Therefore, the label is placed on the battery compartment and on the user manual 10th page. "FCC ID Location" document is bearing the detail label location.

Sincerely Yours,

A handwritten signature in black ink, consisting of a stylized, cursive 'S' followed by a horizontal line and a loop.

Sung-Min Jang
/Representative
/Continental Automotive Systems Corporation

Battery Change Method

At the bottom of the EUT, you can use the key to open the product and change the battery.

