

Company name: Tersus GNSS Inc.
Address: Rm 601, Bldg E2, No. 88, Jinjihu Ave, Suzhou, China
Tel: 86-021-50803061
Fax: 86-021-50803061
Email: chuyang.wang@tersus-gnss.com

Date: 2024-06-17

FEDERAL COMMUNICATIONS COMMISSIONS


Authorization and Evaluation Division

7435 Oakland Mills Road
Columbia, MD 21046

Dear Sir/Madam,

Our product Tersus TC80 Controller, model: TC80, FCC ID: 2AMDJ-TC80, for marketing purpose, this product only supports GSM: 850/1900; WCDMA: Band 2/5; LTE: Band 2/5/7/38/41(band 41:2555-2655MHz),Bluetooth, BLE 1M/2M; 2.4G Wi-Fi (2412-2462 MHz,); 5G Wi-Fi(5150-5250MHz, 5725-5850MHz,); NFC. The other functions, bands were disabled by the software, the end user has no capability to activate it.

Sincerely Yours,



Signature:

Printed Name: Chuyang Wang

Title: Manager