



Intertek Testing Services ETL SEMKO

Report No.: 0008404

Tested By: Hong, Report No.: 0008404


Scan Settings (1 Range)

Frequencies			Receiver Settings				
Start	Stop	Step	IF BW	Detector	M-Time	Atten	
450k	30M	5k	10k	PK	20ms	AUTO LN OFF 60dB	

Final Measurement: x QP

Meas Time: 1 s
Subranges: 16
Acc Margin: 20dB

Transducer No.	Start	Stop	Name
21	5k	30M	EW069C



PAGE 1

Ctrl No.: N/A



Intertek Testing Services

ETL SEMKO

Report No.: 0008404

Tested By: Hong, Report No.: 0008404

Scan Settings (1 Range)

|----- Frequencies -----||----- Receiver Settings -----|

Start	Stop	Step	IF BW	Detector	M-Time	Atten	Preamp	OpRge
450k	30M	5k	10k	PK	20ms	AUTO	LN	OFF 60dB

Final Measurement Results:

Frequency	QP Level	QP Limit
MHz	dBuV	dBuV

0.50000	24.9	48.0
---------	------	------

0.59000	20.6	48.0
---------	------	------

* limit exceeded

Ctrl No.: N/A