

**Conducted Test Setup Placement:**



Front View of the Test Configuration




Side View of the Test Configuration

---

**FCC ID: JVPAWL400**

**Training Research Co., Ltd., TEL: 886-2-26935155, Fax: 886-2-26934440**

***Radiated Test Setup Placement: (Unintentional)***



Front View of the Test Configuration of Unintentional



Rear View of the Test Configuration of Unintentional

---

**FCC ID: JVPAWL400**

**Training Research Co., Ltd., TEL: 886-2-26935155, Fax: 886-2-26934440**

***Radiated Test Setup Placement: (Intentional)***



Front View of the Test Configuration of Intentional



Rear View of the Test Configuration of Intentional

---

***FCC ID: JVPAWL400***

***Training Research Co., Ltd., TEL: 886-2-26935155, Fax: 886-2-26934440***