

ShenZhen Fitcare Electronics Co., Ltd.  
6th floor(south), Building A, Dingxin Science Park Honglang North 2nd Road,  
Bao'an, Shenzhen 518100, China

Apr. 18, 2024

Office of Engineering Technology  
Federal Communications Commission  
7435 Oakland Mills Road  
Columbia, MD 21046  
USA

**Subject: Explanation of differences between product types**

FCC ID: 2ACN7HRM812S  
Models: HRM812S, HRM812, HRM813, HRM814, HRM816,  
HRM817, HRM803, HRM804, HRM805, HRM806, HRM807,  
HRM803S, HRM804S, HR6, HR7, HR8, H6M, PSHR300

To Whom It May Concern:

We, The ShenZhen Fitcare Electronics Co., Ltd. hereby declare that the  
model : HRM812S is identical with the model : HRM812, HRM813, HRM814,  
HRM816, HRM817, HRM803, HRM804, HRM805, HRM806, HRM807,  
HRM803S, HRM804S, HR6, HR7, HR8, H6M, PSHR300, except the model  
name.

Except for the different above, no other modification is performed.

Sincerely,

ShenZhen Fitcare Electronics Co., Ltd.  
Signature:

*Jason Yang*

[Jason Yang, General Manager]