## Mike Kuo

From: S. S. Liou [ssliou@seed.net.tw]

Sent: November24日2003年Monday 8:15 PM

To: Mike Kuo

Subject: Re: Abocom FCC ID:MQ4ARM804, AN03T3370









revised confidential Exhibit-E-User\_Man letter.pd... ual-(NEW).pd...

revised output power test.pdf

revised output power test plot...

Hi Mike,

Ans. #1: Please refer to revised confidential letter. Ans. #2: Please refer to revised user manual.

Ans. #3: Please refer to output power test result and test plot.

Best regards,

\_\_\_\_\_

S. S. Liou

Engineer / EMC Dep. II

ETC

---- Original Message -----

From: "Mike Kuo" <MKUO@CCSEMC.com>

To: "ETC/Iris (E-mail)" <etcemi@seed.net.tw>; "Liou, S. S. (E-mail)"

<ssliou@seed.net.tw>

Sent: Wednesday, November 19, 2003 6:40 AM Subject: Abocom FCC ID:MQ4ARM804, AN03T3370

- > Question #1: User manual is listed as confidential document in the request
- > for confidentiality letter. User manual can not be granted as confidential
- > document. Please remove this item from the letter and provide revised
- > request for confidentiality letter.
- > Question #2: User manual does not contain proper language to address RF
- > exposure compliance. Please provide revised user manual to address this
- > requirement.
- > Question #3: In the channel power measurement, the summation is limited to
- > 6MHz which is less the 6dB bandwidth. Please redo the measurement and
- > provide revised test report and test plots.
- >
- > Best Regards
- > Mike Kuo
- > Compliance Certification Services
- > 561F Monterey Road
- > Morgan Hill CA 95037
- > Tel: (408)463-0885 x: 105
- > Fax: (408)463-0888
- > http://www.ccsemc.com

>