



Please refer to following plots:


Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)



Band 2\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




# Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:45:08

# Band 2\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:45:34

# Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:46:03

# Band 2\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:46:26

# Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:47:00

# Band 2\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:47:26

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:47:55

Band 2\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:48:23

# Band 2\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:48:55

# Band 2\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:49:18

# Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:49:52

# Band 2\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:50:21

# Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:50:53

# Band 2\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:51:18

# Band 2\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:51:54

# Band 2\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:52:22

# Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:52:59

# Band 2\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:53:24

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:53:59

Band 2\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:54:21

# Band 2\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:54:52

# Band 2\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:55:15

# Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:55:53

# Band 2\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:56:15

Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:56:57

Band 2\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:57:23

# Band 2\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:58:01

# Band 2\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:58:27

# Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 14:59:08

# Band 2\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 14:59:30

# Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:00:06

# Band 2\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:00:38

Band 2\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:01:20

Band 2\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:01:42

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:02:17

Band 4\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:02:36

# Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:03:08

# Band 4\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:03:28

# Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:04:03

# Band 4\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:04:28

Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:05:02

Band 4\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:05:28

# Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:06:00

# Band 4\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:06:22

# Band 4\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:06:55

# Band 4\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:07:14

# Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:07:48

# Band 4\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:08:07

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:08:40

Band 4\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:09:05

# Band 4\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:09:34

# Band 4\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:10:00

# Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:10:39

# Band 4\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:10:58

Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:11:33

Band 4\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:11:55

Band 4\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:12:29

Band 4\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:12:52

# Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:13:39

# Band 4\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:13:58

Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:14:40

Band 4\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:15:06

# Band 4\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:15:48

# Band 4\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:16:10

Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:16:55

Band 4\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:17:24

Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:18:09

Band 4\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:18:38

Band 4\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:19:13

Band 4\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-20GHz)




Date: 17.MAR.2021 15:19:42

# Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 18:53:33

# Band 5\_1.4 MHz\_Low\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 18:53:56

Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 18:54:39

Band 5\_1.4 MHz\_Middle\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 18:55:01

# Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 18:55:41

# Band 5\_1.4 MHz\_High\_QPSK\_RB6#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 18:56:10

# Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 18:56:51

# Band 5\_3 MHz\_Low\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 18:57:10

Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 18:57:52

Band 5\_3 MHz\_Middle\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 18:58:09

# Band 5\_3 MHz\_High\_QPSK\_RB15#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 18:58:39

# Band 5\_3 MHz\_High\_QPSK\_RB15#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 18:59:08

# Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 18:59:48

# Band 5\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 19:00:14

# Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:00:53

# Band 5\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 19:01:22

# Band 5\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:01:59

# Band 5\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 19:02:21

Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:02:58

Band 5\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 19:03:21

Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:03:55

Band 5\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 19:04:21

# Band 5\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:04:54

# Band 5\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 5.FEB.2021 19:05:17

# Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:20:19

# Band 7\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:20:45

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:21:18

Band 7\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:21:40

# Band 7\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:22:15

# Band 7\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:22:41

# Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:23:20

# Band 7\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:23:43

Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:24:17

Band 7\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:24:40

Band 7\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:25:04

Band 7\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:25:30

# Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:26:11

# Band 7\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:26:40

Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:27:13

Band 7\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:27:32

# Band 7\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:28:08

# Band 7\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:28:37

Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:29:17

Band 7\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:29:40

Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:30:15

Band 7\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:30:41

# Band 7\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 17.MAR.2021 15:31:23

# Band 7\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 17.MAR.2021 15:31:52

# Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 14.MAR.2021 15:09:41

# Band 17\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 14.MAR.2021 13:30:38

Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 14.MAR.2021 13:31:13

Band 17\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 14.MAR.2021 13:31:33

Band 17\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 14.MAR.2021 13:31:58

Band 17\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-10GHz)




Date: 14.MAR.2021 13:32:18

Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 14.MAR.2021 13:32:54

Band 17\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 14.MAR.2021 13:33:19

Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 14.MAR.2021 13:33:54

Band 17\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 14.MAR.2021 13:34:19

Band 17\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 14.MAR.2021 13:34:54

Band 17\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-10GHz)




Date: 14.MAR.2021 13:35:19

# Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:18:33

# Band 38\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:18:52

Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:19:32

Band 38\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:19:58

# Band 38\_5 MHz\_High\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:20:38

# Band 38\_5 MHz\_High\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:21:01

# Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:21:39

# Band 38\_10 MHz\_Low\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:22:02

Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:22:39

Band 38\_10 MHz\_Middle\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:23:08

# Band 38\_10 MHz\_High\_QPSK\_RB50#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:23:38

# Band 38\_10 MHz\_High\_QPSK\_RB50#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:24:01

# Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:24:50

# Band 38\_15 MHz\_Low\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:25:18

Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:26:00

Band 38\_15 MHz\_Middle\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:26:29

Band 38\_15 MHz\_High\_QPSK\_RB75#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:27:06

Band 38\_15 MHz\_High\_QPSK\_RB75#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:27:29

Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:28:09

Band 38\_20 MHz\_Low\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:28:31

Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:29:16

Band 38\_20 MHz\_Middle\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:29:45

# Band 38\_20 MHz\_High\_QPSK\_RB100#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 19:30:26

# Band 38\_20 MHz\_High\_QPSK\_RB100#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 19:30:52

# Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_1(30MHz-1GHz)




Date: 5.FEB.2021 20:28:08

# Band 41\_5 MHz\_Low\_QPSK\_RB25#0\_2(1GHz-26.5GHz)




Date: 5.FEB.2021 20:28:33

# Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_1(30MHz-1GHz)



Date: 5.FEB.2021 20:29:10

# Band 41\_5 MHz\_Middle\_QPSK\_RB25#0\_2(1GHz-26.5GHz)



Date: 5.FEB.2021 20:29:33