



2_3MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 14:47:16

2_3MHz_Low_16QAM_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 14:46:41

2_3MHz_High_QPSK_1@14




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 14:48:36

2_3MHz_High_QPSK_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 14:48:01

2_3MHz_High_16QAM_1@14




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:21:04

2_3MHz_High_16QAM_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:20:19

2_5MHz_Low_QPSK_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:24:52

2_5MHz_Low_QPSK_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:21:58

2_5MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:26:10

2_5MHz_Low_16QAM_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:25:31

2_5MHz_High_QPSK_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:27:38

2_5MHz_High_QPSK_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:26:59

2_5MHz_High_16QAM_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 16:28:57

2_5MHz_High_16QAM_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 16:28:17

2_10MHz_Low_QPSK_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 16:30:49

2_10MHz_Low_QPSK_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 16:29:59

2_10MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 16:32:29

2_10MHz_Low_16QAM_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 16:31:39

2_10MHz_High_QPSK_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:34:26

2_10MHz_High_QPSK_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 4.JUL.2024 16:11:23

2_10MHz_High_16QAM_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:36:06

2_10MHz_High_16QAM_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:35:15

2_15MHz_Low_QPSK_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:38:20

2_15MHz_Low_QPSK_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 30.JUN.2024 16:37:20

2_15MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 16:40:22

2_15MHz_Low_16QAM_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 16:39:21

2_15MHz_High_QPSK_1@74




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 16:45:03

2_15MHz_High_QPSK_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 4.JUL.2024 16:19:41

2_15MHz_High_16QAM_1@74



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 16:47:07

2_15MHz_High_16QAM_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 16:46:05


FCC Part 24E

B2 , Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0




1.4MHz_High_QPSK_1@5



1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:47:55

1.4MHz_High_16QAM_6@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:47:35

3MHz_Low_QPSK_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:48:53

3MHz_Low_QPSK_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:48:32

3MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:49:37

3MHz_Low_16QAM_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:49:15


3MHz_High_QPSK_1@14




3MHz_High_QPSK_15@0




3MHz_High_16QAM_1@14




3MHz_High_16QAM_15@0




5MHz_Low_QPSK_1@0



5MHz_Low_QPSK_25@0




5MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:53:02

5MHz_Low_16QAM_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:52:19

5MHz_High_QPSK_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:54:00

5MHz_High_QPSK_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:53:18

5MHz_High_16QAM_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:54:47

5MHz_High_16QAM_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:54:25

10MHz_Low_QPSK_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:55:48

10MHz_Low_QPSK_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:55:25

10MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:56:34

10MHz_Low_16QAM_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:56:12

10MHz_High_QPSK_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:57:32

10MHz_High_QPSK_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 11:57:10

10MHz_High_16QAM_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 11:58:20

10MHz_High_16QAM_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 11:57:55

15MHz_Low_QPSK_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 11:59:20

15MHz_Low_QPSK_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 11:58:57

15MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:00:03

15MHz_Low_16QAM_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 11:59:41

15MHz_High_QPSK_1@74




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:01:01

15MHz_High_QPSK_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:00:39

15MHz_High_16QAM_1@74




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:01:48

15MHz_High_16QAM_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:01:26

20MHz_Low_QPSK_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:02:50

20MHz_Low_QPSK_100@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:02:27

20MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:03:36

20MHz_Low_16QAM_100@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:03:13

20MHz_High_QPSK_1@99




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:04:36

20MHz_High_QPSK_100@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:04:12

20MHz_High_16QAM_1@99



ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:05:22

20MHz_High_16QAM_100@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:05:00


FCC Part 27

B4 , Normal


1.4MHz_Low_QPSK_1@0




1.4MHz_Low_QPSK_6@0




1.4MHz_Low_16QAM_1@0




1.4MHz_Low_16QAM_6@0




1.4MHz_High_QPSK_1@5



1.4MHz_High_QPSK_6@0




1.4MHz_High_16QAM_1@5




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:08:48

1.4MHz_High_16QAM_6@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:08:26

3MHz_Low_QPSK_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:09:48

3MHz_Low_QPSK_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:09:26

3MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:10:31

3MHz_Low_16QAM_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
 Date: 28.JUN.2024 12:10:10

3MHz_High_QPSK_1@14




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:11:28

3MHz_High_QPSK_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:11:06

3MHz_High_16QAM_1@14




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:12:12

3MHz_High_16QAM_15@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:11:49

5MHz_Low_QPSK_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:13:14

5MHz_Low_QPSK_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:12:50

5MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:14:02

5MHz_Low_16QAM_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:13:38

5MHz_High_QPSK_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:15:02

5MHz_High_QPSK_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:14:38

5MHz_High_16QAM_1@24




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:15:50

5MHz_High_16QAM_25@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:15:25

10MHz_Low_QPSK_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:16:55

10MHz_Low_QPSK_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:16:30

10MHz_Low_16QAM_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:17:44

10MHz_Low_16QAM_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:17:19

10MHz_High_QPSK_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:23:22

10MHz_High_QPSK_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 30.JUN.2024 17:43:00

10MHz_High_16QAM_1@49




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:24:08

10MHz_High_16QAM_50@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:23:46

15MHz_Low_QPSK_1@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:25:12

15MHz_Low_QPSK_75@0




ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:24:48

15MHz_Low_16QAM_1@0



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:26:00

15MHz_Low_16QAM_75@0



ProjectNo.:2402U82788E-RF Tester:Karl Liang
Date: 28.JUN.2024 12:25:36