

EMC Technologies Report Number: M060760_Cert_AR5BXB6_NII_BT

APPENDIX K

HARMONICS



Harmonics – Channel 36

Marker 1 [T1]


RBW 300 kHz RF Att 30 dB

Ref Lvl 6.95 dBm

VBW 1 MHz

15 dBm 5.14228457 GHz

SWT 1.1 s Unit dBm




Date: 20.FEB.2006 11:58:25



Harmonics - Channel 52

Marker 1 [T1]	RBW	300 kHz	RF Att	30 dB
Ref Lvl	7.08 dBm	VBW	1 MHz	
15 dBm	5.22044088 GHz	SWT	1.1 s	Unit dBm




Date: 20.FEB.2006 12:00:45



Harmonics - Channel 64

Marker 1 [T1] RBW 300 kHz RF Att 30 dB
Ref Lvl 6.89 dBm VBW 1 MHz
15 dBm 5.29859719 GHz SWT 1.1 s Unit dBm




Date: 20.FEB.2006 12:02:51



Harmonics - Channel 100

Ref Lvl	Marker 2 [T1]	RBW	300 kHz	RF Att	30 dB
15 dBm	-51.18 dBm	VBW	1 MHz		
	11.00400802 GHz	SWT	1.1 s	Unit	dBm




Date: 8.MAR.2006 09:35:59



Harmonics - Channel 120

Date: 8.MAR.2006 09:33:25



Harmonics - Channel 140

Date: 8.MAR.2006 09:29:48

