## Label

## tangent

191 Airport Boulevard Burlingame, CA 94010 1-888-TANGENT www.tangent.com

FCC ID: II7OEM-805N21XU Contains FCC ID: II78265NG







MEDICAL EQUIPMENT WITH RESPECT TO ELECTRIC SHOCK FIRE AND MECHANICAL HAZARDS ONLY IN ACCORDANCE WITH ANSI/AAMI ES60601-1 AND CAN/CAS-C22 No 60601-1

US CUL



Input: 19V --- 4.74A

This device complies with Part 15 of the FCC Rules. Operation is subject to the following two conditions: (1) this device may not cause harmful interference, and (2) this device must accept any interference received, including interference that may cause undesired operation.

Made in Taiwan

## Label location

