

May 6, 2019

Timco Engineering, Inc.  
849 NW State Road 45  
P.O. Box 370  
Newberry, Florida 32669

Re: Justification for Label Location

FCC: 2AD9X-KF2GIG

To Whom It May Concern:

Per our label location exhibit, we will place our label on the inside of the housing Lid. The outside of the small sensor housing would degrade the appearance of the sensor. The inside of the Lid is easily accessible and visible when accessing the battery.

Sincerely,

A handwritten signature in black ink, appearing to read "P. Justin Carlson".

Justin Carlson  
General Manager  
Versa Wireless Inc.  
103 - 19292 60<sup>th</sup> Avenue  
Surrey, BC V3S 3M2  
Canada