
TEST REPORT: 73-6689 FCC ID: AS5LTIMDW9G


Page 91 of 108

Exhibit 9: Internal Photographs




Inside View (Base)

TEST REPORT: 73-6689 FCC ID: AS5LTIMDW9G Page 92 of 108



Component Side of PCB with RF cans installed (Base)

TEST REPORT: 73-6689 FCC ID: AS5LTIMDW9G Page 93 of 108



Opposite Side of PCB with RF cans removed (Base)


TEST REPORT: 73-6689 FCC ID: AS5LTIMDW9G

Page 94 of 108




Opposite Side of PCB (Base)

TEST REPORT: 73-6689 FCC ID: AS5LTIMDW9G Page 95 of 108



Component Side of PCB (Handset)

TEST REPORT: 73-6689 FCC ID: AS5LTIMDW9G Page 96 of 108



Opposite Side of PCB (Handset)