



FCC - TEST REPORT
Appendix A for 709502403251-00C

Table of Contents

1	Duty Cycle.....	2
2	Maximum Conducted Output Power	44
3	-26dB Bandwidth	223
4	Occupied Channel Bandwidth	101
5	Maximum Power Spectral Density Level	158
6	Frequency Stability.....	215
7	-6dB Bandwidth.....	223



1 Duty Cycle

Condition	Mode	Frequency (MHz)	Antenna	Duty Cycle (%)	Correction Factor (dB)
NVNT	a	5180	Ant1	93.51	0.29
NVNT	a	5200	Ant1	93.51	0.29
NVNT	a	5240	Ant1	93.51	0.29
NVNT	a	5745	Ant1	93.44	0.29
NVNT	a	5785	Ant1	93.44	0.29
NVNT	a	5825	Ant1	93.44	0.29
NVNT	a	5180	Ant2	93.44	0.29
NVNT	a	5200	Ant2	93.51	0.29
NVNT	a	5240	Ant2	93.51	0.29
NVNT	a	5745	Ant2	93.51	0.29
NVNT	a	5785	Ant2	93.44	0.29
NVNT	a	5825	Ant2	93.51	0.29
NVNT	a	5180	Sum	93.44	0.29
NVNT	a	5200	Sum	93.44	0.29
NVNT	a	5240	Sum	93.51	0.29
NVNT	a	5745	Sum	93.44	0.29
NVNT	a	5785	Sum	93.51	0.29
NVNT	a	5825	Sum	93.51	0.29
NVNT	n20	5180	Ant1	93.11	0.31
NVNT	n20	5200	Ant1	93.11	0.31
NVNT	n20	5240	Ant1	93.03	0.31
NVNT	n20	5745	Ant1	93.1	0.31
NVNT	n20	5785	Ant1	93.03	0.31
NVNT	n20	5825	Ant1	93.1	0.31
NVNT	n20	5180	Ant2	93.03	0.31
NVNT	n20	5200	Ant2	93.03	0.31
NVNT	n20	5240	Ant2	93.03	0.31
NVNT	n20	5745	Ant2	93.03	0.31
NVNT	n20	5785	Ant2	93.03	0.31
NVNT	n20	5825	Ant2	93.11	0.31
NVNT	n20	5180	Sum	93.03	0.31
NVNT	n20	5200	Sum	93.03	0.31
NVNT	n20	5240	Sum	93.03	0.31
NVNT	n20	5745	Sum	93.03	0.31
NVNT	n20	5785	Sum	93.11	0.31
NVNT	n20	5825	Sum	93.11	0.31
NVNT	n40	5190	Ant1	87.01	0.6
NVNT	n40	5230	Ant1	86.88	0.61
NVNT	n40	5755	Ant1	86.88	0.61
NVNT	n40	5795	Ant1	87.01	0.6
NVNT	n40	5190	Ant2	87.01	0.6
NVNT	n40	5230	Ant2	86.88	0.61
NVNT	n40	5755	Ant2	86.88	0.61
NVNT	n40	5795	Ant2	0	0
NVNT	n40	5190	Sum	86.9	0.61
NVNT	n40	5230	Sum	86.88	0.61
NVNT	n40	5755	Sum	86.88	0.61
NVNT	n40	5795	Sum	87.01	0.6
NVNT	ac20	5180	Ant1	99.13	0
NVNT	ac20	5200	Ant1	99.13	0
NVNT	ac20	5240	Ant1	99.08	0
NVNT	ac20	5745	Ant1	99.13	0
NVNT	ac20	5785	Ant1	99.13	0
NVNT	ac20	5825	Ant1	99.13	0
NVNT	ac20	5180	Ant2	99.08	0
NVNT	ac20	5200	Ant2	99.13	0
NVNT	ac20	5240	Ant2	99.08	0
NVNT	ac20	5745	Ant2	99.08	0
NVNT	ac20	5785	Ant2	99.13	0
NVNT	ac20	5825	Ant2	99.08	0
NVNT	ac20	5180	Sum	99.08	0
NVNT	ac20	5200	Sum	99.08	0
NVNT	ac20	5240	Sum	99.13	0
NVNT	ac20	5745	Sum	99.08	0
NVNT	ac20	5785	Sum	99.08	0



NVNT	ac20	5825	Sum	99.08	0
NVNT	ac40	5190	Ant1	98.91	0
NVNT	ac40	5230	Ant1	98.91	0
NVNT	ac40	5755	Ant1	98.91	0
NVNT	ac40	5795	Ant1	98.91	0
NVNT	ac40	5190	Ant2	98.85	0
NVNT	ac40	5230	Ant2	98.91	0
NVNT	ac40	5755	Ant2	98.85	0
NVNT	ac40	5795	Ant2	98.91	0
NVNT	ac40	5190	Sum	98.85	0
NVNT	ac40	5230	Sum	98.85	0
NVNT	ac40	5755	Sum	98.91	0
NVNT	ac40	5795	Sum	98.91	0
NVNT	ac80	5210	Ant1	0	0
NVNT	ac80	5775	Ant1	86.01	0.65
NVNT	ac80	5210	Ant2	85.96	0.66
NVNT	ac80	5775	Ant2	86.04	0.65
NVNT	ac80	5210	Sum	85.96	0.66
NVNT	ac80	5775	Sum	85.96	0.66
NVNT	ax20	5180	Ant1	91.25	0.4
NVNT	ax20	5200	Ant1	91.33	0.39
NVNT	ax20	5240	Ant1	91.34	0.39
NVNT	ax20	5745	Ant1	91.33	0.39
NVNT	ax20	5785	Ant1	91.25	0.4
NVNT	ax20	5825	Ant1	91.34	0.39
NVNT	ax20	5180	Ant2	91.33	0.39
NVNT	ax20	5200	Ant2	91.34	0.39
NVNT	ax20	5240	Ant2	91.07	0.41
NVNT	ax20	5745	Ant2	91.33	0.39
NVNT	ax20	5785	Ant2	91.25	0.4
NVNT	ax20	5825	Ant2	91.34	0.39
NVNT	ax20	5180	Sum	91.33	0.39
NVNT	ax20	5200	Sum	91.33	0.39
NVNT	ax20	5240	Sum	91.34	0.39
NVNT	ax20	5745	Sum	91.34	0.39
NVNT	ax20	5785	Sum	91.25	0.4
NVNT	ax20	5825	Sum	91.25	0.4
NVNT	ax40	5190	Ant1	84.69	0.72
NVNT	ax40	5230	Ant1	84.84	0.71
NVNT	ax40	5755	Ant1	84.69	0.72
NVNT	ax40	5795	Ant1	84.84	0.71
NVNT	ax40	5190	Ant2	84.84	0.71
NVNT	ax40	5230	Ant2	84.69	0.72
NVNT	ax40	5755	Ant2	84.84	0.71
NVNT	ax40	5795	Ant2	84.84	0.71
NVNT	ax40	5190	Sum	84.69	0.72
NVNT	ax40	5230	Sum	84.84	0.71
NVNT	ax40	5755	Sum	84.84	0.71
NVNT	ax40	5795	Sum	84.84	0.71
NVNT	ax80	5210	Ant1	75.13	1.24
NVNT	ax80	5775	Ant1	74.87	1.26
NVNT	ax80	5210	Ant2	75.13	1.24
NVNT	ax80	5775	Ant2	75.06	1.25
NVNT	ax80	5210	Sum	74.87	1.26
NVNT	ax80	5775	Sum	74.87	1.26































































