







Band2_3MHz_16QAM_18615_1RB#0_0.15~30_0.15
~30



Band2_3MHz_16QAM_18615_1RB#0_30~1000_30~
1000





Band2_3MHz_16QAM_18615_1RB#0_1000~3000_1
000~3000





Band2_3MHz_16QAM_18615_1RB#0_3000~20000_
3000~20000




















Band2_5MHz_QPSK_18625_1RB#0_0.009~0.15_0.0
09~0.15



Band2_5MHz_QPSK_18625_1RB#0_0.15~30_0.15~
30







Band2_5MHz_QPSK_18625_1RB#0_30~1000_30~1
000





Band2_5MHz_QPSK_18625_1RB#0_1000~3000_10
00~3000







Shenzhen LCS Compliance Testing Laboratory Ltd.
Add: 101, 201 Bldg A & 301 Bldg C, Juji Industrial Park Yabianxueziwei, Shajing Street, Baoan District, Shenzhen,
518000, China
Tel: +(86) 0755-82591330 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com
Scan code to check authenticity









Band2_5MHz_16QAM_18900_1RB#0_0.15~30_0.15
~30



Band2_5MHz_16QAM_18900_1RB#0_30~1000_30~
1000




Band2_5MHz_16QAM_18900_1RB#0_1000~3000_1
000~3000




Band2_5MHz_16QAM_18900_1RB#0_3000~20000_
3000~20000







Band2_5MHz_QPSK_19175_1RB#0_0.009~0.15_0.09~0.15



Band2_5MHz_QPSK_19175_1RB#0_0.15~30_0.15~30




Band2_5MHz_QPSK_19175_1RB#0_30~1000_30~1000




Band2_5MHz_QPSK_19175_1RB#0_1000~3000_1000~3000








Band2_5MHz_16QAM_19175_1RB#0_0.009~0.15_0.009~0.15




Band2_5MHz_16QAM_19175_1RB#0_30~1000_30~1000









Band2_10MHz_QPSK_18650_1RB#0_30~1000_30~1000



Band2_10MHz_QPSK_18650_1RB#0_1000~3000_1000~3000





Band2_10MHz_QPSK_18650_1RB#0_3000~20000_3000~20000




Band2_10MHz_16QAM_18650_1RB#0_0.009~0.15_0.009~0.15












Band2_10MHz_QPSK_18900_1RB#0_3000~20000_3000~20000



Band2_10MHz_16QAM_18900_1RB#0_0.009~0.15_0.009~0.15





Band2_10MHz_16QAM_18900_1RB#0_0.15~30_0.15~30




Band2_10MHz_16QAM_18900_1RB#0_30~1000_30~1000












Band2_10MHz_16QAM_19150_1RB#0_0.15~30_0.1
5~30



Band2_10MHz_16QAM_19150_1RB#0_30~1000_30
~1000




Band2_10MHz_16QAM_19150_1RB#0_1000~3000_
1000~3000




Band2_10MHz_16QAM_19150_1RB#0_3000~20000
_3000~20000







Band2_15MHz_QPSK_18675_1RB#0_0.009~0.15_0.009~0.15



Band2_15MHz_QPSK_18675_1RB#0_0.15~30_0.15~30




Band2_15MHz_QPSK_18675_1RB#0_30~1000_30~1000




Band2_15MHz_QPSK_18675_1RB#0_1000~3000_1000~3000







Band2_15MHz_QPSK_18675_1RB#0_3000~20000_3000~20000



Band2_15MHz_16QAM_18675_1RB#0_0.009~0.15_0.009~0.15



Band2_15MHz_16QAM_18675_1RB#0_0.15~30_0.15~30



Band2_15MHz_16QAM_18675_1RB#0_30~1000_30~1000

