

Fanvil Technology Co., LTD.

Address: 10/F Block A, Dualshine Global Science Innovation HonglangNorth 2nd Road,  
Bao'an District, Shenzhen, 518101, China

Tel: 86-0755-26402199 Fax:86-0755-26402618

Email: [mengjiao.Hu@fanvil.com](mailto:mengjiao.Hu@fanvil.com)

The RF chip, model: **RTL8761BTV**, installed in our product IP Phone,  
model: X6U V2,FCC ID: 2APPZ-X6UV2, this chip supports EDR( $\pi/4$ -DQPSK,8DPSK),  
BDR(GFSK) and BLE1M/2M function, but for marketing purpose, this chip only supports  
EDR( $\pi/4$ -DQPSK,8DPSK), BDR(GFSK) and BLE1M. The BLE 2M was disabled to use by  
manufacture in the software, the end user has no capability to activate it.

Sincerely,

Signature: *Mengjiao Hu*

Mengjiao Hu

Certified Engineer