

Intertek Testing Services Hong Kong Limited Tel +852 2173 8888 2/F, Garment Centre Fax +852 2786 1903 576 Castle Peak Road intertek.com Kowloon Hong Kong

Device: DFB RC BoAndFlash SLD (89418, 1088486, 6068379), DFB VHC RC Core BoAndFlash ECMX SLD (1089825, 6069602)

FCC ID: PQN89418TX2G4

Chipset/module information:

#	Chipset/module part number	Memory size
1	PAN2010	OTP: 8KBytes
2		

Operating System (as applicable): N/A

Storage Capacity (hard drive or other permanent memory storage): 8KBytes

Device features:

#	Feature	Yes / No
1	Designed not intended for software/program installation	Yes
2	Chipset/module has limited memory that is insufficient for the manufacturer to burn/pre-install programs/applications	Yes
3	No internet connection	Yes
4	No connector/port for computer connection	Yes

Justification: Based on the review of the above factsheet(s) and device features, the device cannot support installation of Kaspersky cybersecurity or anti-virus software.

Name: Jess Tang

Date: May 26, 2025