

## William Graff

---

**From:** Roger Sheng (???) [Roger@sporton.com.tw]  
**Sent:** Wednesday, December 28, 2005 5:37 PM  
**To:** William Graff  
**Cc:** Landy Soong (???)  
**Subject:** FW: 780-706

Dear Bill

Got response from customer.

The name on the Grant: *Wireless Residential DSL Gateway with Voice*.  
Customer's declaration email is show below.

Please help for the FCC/IC Grant.

If you have any question, please don't hesitate to contact us.  
Best Regards,

Roger Sheng (盛念伯)

Manager / Radio Business  
Sporton International Inc.  
Hsinchu Division: No. 8, Lane 724, Bo Ai Street, Zhubei City,  
Hsin Chu Hsien 302, Taiwan R.O.C.  
Tel: +886 3 3273456 ext. 547  
Fax: +886 3 6569085  
Mobile: 886 939226484  
[www.sporton.com.tw](http://www.sporton.com.tw)

---

**From:** Pony Chang (張文政)  
**Sent:** Wednesday, December 28, 2005 5:29 PM  
**To:** Roger Sheng (盛念伯)  
**Cc:** Landy Soong (宋李蘭)  
**Subject:** FW: 780-706

---

**From:** Jovy [mailto:joy@askey.com.tw]  
**Sent:** Wednesday, December 28, 2005 5:22 PM  
**To:** Pony Chang (張文政)  
**Subject:** 780-706

Dear Pony,

1.  
Product name:  
*Wireless Residential DSL Gateway with Voice*
2.  
The product codes and are used to restrict the software configurations for the specified regions.  
The table below shows the product codes specified in North America.  
The units with the listed product codes are ONLY available from channel 1 to 11 for user's wireless configuration.

Users cannot find channel 12 or upper from the installation interface.

Equipment	Model Number
SpeedTouch 780 WL	DSLBB643 EB
SpeedTouch 780 WL	DSLBB643 EE
SpeedTouch 706 WL	DSLBB643 ED
SpeedTouch 706 WL	DSLBB843 ED
SpeedTouch 706 WL	DSLBB643 EF

Best Regards,

Jovy Yang

+ 886 2 22287588 ext 1722

EMC Section

Product Certification Division

ASKEY Computer Corp.

Message has been scanned by Sporton AntiVirus System with no virus detected.