

## F.C.C. GUIDELINES

1

WARNING: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to Part 15 of the FCC Rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation.

This equipment generates, Uses and can radiated radio frequency energy and if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation.

If this equipment does cause harmful interference to radio or television reception, which can be determined by turning the equipment off and on, the user is encouraged to try to correct the interference by one or more of the following measures:

- Reorient or relocate the receiving antenna.
  - Increase the separation between the equipment and receiver.
  - Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
  - Consult the dealer or an experienced radio/TV technician for help.
- Shielded interface cables must be used in order to comply with emission limits.  
Changes or modifications not expressly approved by the party responsible for compliance could void the user's authority to operate the equipment.

## Bescheinigung des Herstellers/Importeurs

---

in Übereinstimmung mit den Bestimmungen der BMPT-AmtsblVfg 243/1991 funk-entstört ist.  
Der vorschriftsmäßige Betrieb mancher Geräte (z.B. McBsender) kann allerdings gewissen  
Hinshrankungen unterliegen. Beachten Sie deshalb die Hinweise in der Bedienungsanleitung.  
Dem Bundesamt für Zulassungen in der Telekommunikation wurde das Inverkehrbringen dieses  
Gerätes angezeigt und die Berechtigung zur Überprüfung der Serie auf die Einhaltung der  
Bestimmungen eingeräumt.