




Product Service

FCC ID: 2AL6R-ESGL01  
IC: 22758-ESGL01

BCF Technology Limited  
Easi Scan:Go Bovine Scanner



#### PHOTOGRAPHS OF TEST SET UP




Radiated Emissions 30 MHz to 1 GHz




Product Service

FCC ID: 2AL6R-ESGL01  
IC: 22758-ESGL01

BCF Technology Limited  
Easi Scan:Go Bovine Scanner



Radiated Emissions 1 GHz to 18 GHz



Radiated Emissions 18 GHz to 30 GHz



Product Service

FCC ID: 2AL6R-ESGL01  
IC: 22758-ESGL01



B A B T

BCF Technology Limited  
Easi Scan:Go Bovine Scanner



Front Face – Upper



Front Face - Lower



Product Service

FCC ID: 2AL6R-ESGL01  
IC: 22758-ESGL01



BCF Technology Limited  
Easi Scan:Go Bovine Scanner



Top Edge



Bottom Edge





Product Service

FCC ID: 2AL6R-ESGL01  
IC: 22758-ESGL01

BCF Technology Limited  
Easi Scan:Go Bovine Scanner



Right Edge - Lower




Right Edge - Upper



Product Service

FCC ID: 2AL6R-ESGL01  
IC: 22758-ESGL01

BCF Technology Limited  
Easi Scan:Go Bovine Scanner



Left Edge - Lower



Left Edge - Upper



Product Service

FCC ID: 2AL6R-ESGL01  
IC: 22758-ESGL01

BCF Technology Limited  
Easi Scan:Go Bovine Scanner



Product Service



Rear Face