

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs




Figure 1 – Front with 25mm Separation



Figure 2 – Front with 25mm Separation (antenna extended)

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs




Figure 3 – Front with 0mm Separation



Figure 4 – Back with 0mm Separation

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs



Figure 5 – Right with 0mm Separation



Figure 6 – Top with 0mm Separation

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs



Figure 7 – Front with 0mm Separation (antenna extended)



Figure 8 – Back with 0mm Separation (antenna extended)

INTERTEK TESTING SERVICES

The Worst Case Configuration Photographs



Figure 9 – Right with 0mm Separation (antenna extended)



Figure 10 – Top with 0mm Separation (antenna extended)