

Icom America, Inc.

Corporate Headquarters 2380 116th Ave. N.E. Bellevue, Washington 98004 Phone: (425) 454-8155 Fax: (425) 454-1509 Customer Service: (425) 454-7619

December 3, 1999

Federal Communications Commission Authorization & Evaluation Division 7435 Oakland Mills Road Columbia, Maryland 21046

Attention:

Authorization & Evaluation Division

Applicant:

ICOM INCORPORATED

Equipment: FCC ID: AFJIC-R2

FCC Rules: Part 2.1043

Subject:

Updated information for Class II Permissive Change

Dear Sir/Madam

In order to comply with new FCC scanner regulation, a permanently affixed warning label has been attached to the products as per FCC Part 15.121 (f)(1).

Otherwise, the device is internally and electronically same.

Thekh

Best regards

Masaaki Takahashi

Manager, New Product Development

MT:sg