

To: Greg Snyder
Subject: HET_L9W-C5434-TX

Importance: High

Greg,

The following items must be provided before this application can procede.

- 1.) It is impossible to detirmine from the single page operational description provided that this is an FM system. Please provide more detail.
- 2.) The occupied bandwidth provided in the test report is taken with too wide a resolution bandwidth to be useful. In general, an occupied bandwidth for any system should use an measurement bandwidth as close as possible, but not less than 1% of the 20dB bandwidth. Using the measured 348 KHz 20 dB bandwidth in Exhibit 1, this would make the resolution BW close to, but not less than 3.48KHz. To be safe, I suggest taking two plots, one with 3KHz and one with 10KHz RBW. Please provide.

Thanks,

Bill

~~~~~  
~ William H. Graff, NARTE Certified  
~ Vice President of Engineering  
~ AmericanTCB, Inc.  
~ 6731 Whittier Avenue  
~ McLean, VA 22101  
~ mailto:billg@AmericanTCB.com  
~ http://www.AmericanTCB.com  
~ Tel: (703)847-4700 Fax: (703)847-6889  
~ Mobile: (602)790-6788  
~~~~~