Company: Signify North America Corporation Add: 10275 W. Higgins Rd., Rosemont, Illinois 60018, United States Tel: 847-390-5195 Fax: 847-390-5264 E-mail: richard.haring@signify.com

Attestation Letter

Date: 2025-03-27

FEDERAL COMMUNICATIONS COMMISSION Authorization and Evaluation Division 7435 Oakland Mills Road Columbia, MD 21046

The RF Chip installed in our product: LED Luminaire, Model: 9290046315, 9290046318 FCC ID: 2AF2N-929004631X, only support BLE 1M 2402-2480MHz function. The other function and frequency shielded by the manufacturer using the software, the end user has no capability to activate it.

Best Regards,

Avin Signature:

Contact Person: Arun Ganesh Title: R&D Manager