Class II change apply for WLP020(From WLP020 FCC ID: H8N-WLP020)

 $Modified 1: the \ layout \ from \ the \ Baseband \ IC \ , Ethernet \ IC \ each \ side \ top \ and \ bottom \ layer$ to them are same as side on top layer.

Modified2: the antenna pad of MMCX to Hirose pad.



