## **INTERTEK TESTING SERVICES**

## **The Worst Case Configuration Photographs**



Figure 1 – Right Cheek




Figure 2 – Left Cheek

FCC ID: ACJ9TAWX-CH457P IC: 216A-WXCH457P