

Non-Conformities FCC ID: MI7-IPB800 (Ref # E06-000151-1)

The items listed below represent requests for information following review of this application. Further question may arise pending review of responses to these items.

OK	#	Non-Conformity or Comment	Submitted Response	Respondent / Date of Response
NC -2	1	Please explain the bandwidth change from 20kHz to 10kHz necessary bandwidth.	Changed to 20KF1D, but this change is unjustified.	CKC Labs 5/23/06
Y	2	Why was antenna port conducted data only provided in graphical form for 1-30MHz only? Typically graphical data is provided for the entire frequency range.	Incorrect plot removed from test report. Tabular data supports compliance.	CKC Labs 5/23/06
Y	3	Test report references RSS 119, does application wish to pursue IC Certification also?	Not at this time.	CKC Labs 5/23/06

Non-Conformities FCC ID: MI7-IPB800 (Ref # E06-000151-2)

The items listed below represent requests for information following review of this application. Further question may arise pending review of responses to these items.

OK	#	Non-Conformity or Comment	Submitted Response	Respondent / Date of Response
Y	1	Please explain the bandwidth change from 20kHz to 10kHz necessary bandwidth. The Emissions designator has been changed, however, there is no justification for this bandwidth. Please provide information regarding the nature of the change of the necessary bandwidth of the equipment.	Necessary bandwidth justified by calculation method.	CKC Labs 5/25/06

The items indicated above must be submitted before processing can continue on the referenced application. Failure to provide the requested information within 60 days may result in application dismissal pursuant to Section 2.917(c) and forfeiture of the filing fee pursuant to Section 1.1106.