


Appendix B


Please refer to following plots:

Band 2_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:30:08

Band 2_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:30:31

Band 2_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:31:08

Band 2_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:31:31

Band 2_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:32:05

Band 2_1.4 MHz_High_QPSK_RB6#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:32:28

Band 2_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:33:07

Band 2_3 MHz_Low_QPSK_RB15#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:33:29

Band 2_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:33:54

Band 2_3 MHz_Middle_QPSK_RB15#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:34:16

Band 2_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:34:51

Band 2_3 MHz_High_QPSK_RB15#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:35:20

Band 2_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:35:56

Band 2_5 MHz_Low_QPSK_RB25#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:36:21

Band 2_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:36:56

Band 2_5 MHz_Middle_QPSK_RB25#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:37:15

Band 2_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:37:49

Band 2_5 MHz_High_QPSK_RB25#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:38:18

Band 2_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:38:50

Band 2_10 MHz_Low_QPSK_RB50#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:39:15

Band 2_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:39:52

Band 2_10 MHz_Middle_QPSK_RB50#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:40:14

Band 2_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:40:48

Band 2_10 MHz_High_QPSK_RB50#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:41:13

Band 2_15 MHz_Low_QPSK_RB75#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:41:47

Band 2_15 MHz_Low_QPSK_RB75#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:42:15

Band 2_15 MHz_Middle_QPSK_RB75#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:42:57

Band 2_15 MHz_Middle_QPSK_RB75#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:43:19

Band 2_15 MHz_High_QPSK_RB75#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:43:57

Band 2_15 MHz_High_QPSK_RB75#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:44:22

Band 2_20 MHz_Low_QPSK_RB100#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:44:59

Band 2_20 MHz_Low_QPSK_RB100#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:45:27

Band 2_20 MHz_Middle_QPSK_RB100#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:46:05

Band 2_20 MHz_Middle_QPSK_RB100#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:46:24

Band 2_20 MHz_High_QPSK_RB100#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:46:56

Band 2_20 MHz_High_QPSK_RB100#0_2(1GHz-20GHz)




Date: 21.APR.2022 17:47:25

Band 5_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:48:01

Band 5_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:48:26

Band 5_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:48:55

Band 5_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:49:20

Band 5_1.4 MHz_High_QPSK_RB6#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:49:55

Band 5_1.4 MHz_High_QPSK_RB6#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:50:17

Band 5_3 MHz_Low_QPSK_RB15#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:50:53

Band 5_3 MHz_Low_QPSK_RB15#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:51:18

Band 5_3 MHz_Middle_QPSK_RB15#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:51:47

Band 5_3 MHz_Middle_QPSK_RB15#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:52:12

Band 5_3 MHz_High_QPSK_RB15#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:52:41

Band 5_3 MHz_High_QPSK_RB15#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:53:09

Band 5_5 MHz_Low_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:53:48

Band 5_5 MHz_Low_QPSK_RB25#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:54:13

Band 5_5 MHz_Middle_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:54:45

Band 5_5 MHz_Middle_QPSK_RB25#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:55:07

Band 5_5 MHz_High_QPSK_RB25#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:55:45

Band 5_5 MHz_High_QPSK_RB25#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:56:08

Band 5_10 MHz_Low_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:56:49

Band 5_10 MHz_Low_QPSK_RB50#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:57:11

Band 5_10 MHz_Middle_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:57:48

Band 5_10 MHz_Middle_QPSK_RB50#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:58:10

Band 5_10 MHz_High_QPSK_RB50#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:58:44

Band 5_10 MHz_High_QPSK_RB50#0_2(1GHz-10GHz)




Date: 21.APR.2022 17:59:06

Band 12_1.4 MHz_Low_QPSK_RB6#0_1(30MHz-1GHz)




Date: 21.APR.2022 17:59:39

Band 12_1.4 MHz_Low_QPSK_RB6#0_2(1GHz-10GHz)




Date: 21.APR.2022 18:00:01

Band 12_1.4 MHz_Middle_QPSK_RB6#0_1(30MHz-1GHz)



Date: 21.APR.2022 18:00:30

Band 12_1.4 MHz_Middle_QPSK_RB6#0_2(1GHz-10GHz)



Date: 21.APR.2022 18:00:49