



10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:06:57

10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:07:41

10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@23 -37.62 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:48:45

10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@23 -46.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:47:58

10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB24@0 -37.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:50:04

10MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB24@0 -47.31 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:49:17

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB1@0 -36.69 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:10:50

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB1@0 -47.70 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:10:05

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB1@23 -37.72 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:56:06

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB1@23 -47.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:55:19

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB24@0 -36.90 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:57:25

10MHz_30kHz_2685MHz_DFT-s-OFDM QPSK_RB24@0 -46.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:56:39

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:13:26

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@0 -46.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:12:40

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@78 -46.27 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:13:59

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@78 -37.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:14:45

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB75@0 -37.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:16:03

15MHz_15kHz_2503.5MHz_DFT-s-OFDM QPSK_RB75@0 -46.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:15:17

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -47.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:17:48

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -37.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:18:34

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@78 -37.55 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:19:53

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@78 -47.77 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:19:07

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB75@0 -35.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:21:12

15MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB75@0 -46.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:20:25

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB1@0 -37.10 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 18:57:57

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB1@0 -47.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 18:57:12

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB1@78 -47.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:26:31

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB1@78 -37.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:27:20

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB75@0 -37.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:28:39

15MHz_15kHz_2682.495MHz_DFT-s-OFDM QPSK_RB75@0 -46.52 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:27:52

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@0 -47.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:58:39

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@0 -37.44 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:59:25

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@37 -37.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:00:44

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB1@37 -47.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:59:58

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB36@0 -37.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:02:04

15MHz_30kHz_2503.5MHz_DFT-s-OFDM QPSK_RB36@0 -47.61 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:01:17

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:04:04

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:03:17

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@37 -36.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:05:24

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@37 -46.87 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:04:37

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB36@0 -47.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:05:56

15MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB36@0 -37.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:06:43

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB1@0 -37.23 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:15:04

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB1@0 -47.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:14:19

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB1@37 -36.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:12:49

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB1@37 -47.37 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:12:02

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB36@0 -47.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:13:21

15MHz_30kHz_2682.48MHz_DFT-s-OFDM QPSK_RB36@0 -36.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:14:08

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB1@0 -37.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:30:39

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB1@0 -46.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:29:52

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB1@105 -37.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:31:57

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB1@105 -47.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:31:11

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB100@0 -47.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:32:30

20MHz_15kHz_2506.005MHz_DFT-s-OFDM QPSK_RB100@0 -37.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:33:16

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -36.73 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:35:15

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -46.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:34:29

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@105 -37.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:36:34

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@105 -47.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:35:47

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB100@0 -34.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:37:05

20MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB100@0 -37.06 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:37:52

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:41:12

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:41:59

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@105 -47.53 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:42:57

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@105 -37.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:43:44

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB100@0 -46.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:44:17

20MHz_15kHz_2679.99MHz_DFT-s-OFDM QPSK_RB100@0 -37.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:45:03

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB1@0 -46.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:15:21

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB1@0 -36.65 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:16:08

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB1@50 -37.18 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:17:28

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB1@50 -47.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:16:41

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB50@0 -37.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:18:49

20MHz_30kHz_2506.02MHz_DFT-s-OFDM QPSK_RB50@0 -47.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:18:02

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.17 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:20:48

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -46.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:20:02

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@50 -37.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:22:08

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@50 -47.63 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:21:21

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB50@0 -36.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:23:28

20MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB50@0 -46.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:22:41

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:16:56

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.34 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:16:11

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@50 -47.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:17:25

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB1@50 -37.59 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:18:09

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB50@0 -47.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:30:35

20MHz_30kHz_2679.99MHz_DFT-s-OFDM QPSK_RB50@0 -37.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:31:21

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB1@0 -46.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:46:17

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB1@0 -37.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:47:03

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB1@159 -37.21 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:48:22

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB1@159 -47.36 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:47:36

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB160@0 -47.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:48:55

30MHz_15kHz_2511MHz_DFT-s-OFDM QPSK_RB160@0 -37.52 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:49:41

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -43.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:50:54

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -37.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:51:41

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@159 -47.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:52:14

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@159 -37.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:53:01

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB160@0 -41.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:53:33

30MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB160@0 -37.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:54:20

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB1@0 -47.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:23:15

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB1@0 -37.41 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:23:59

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB1@159 -37.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:00:18

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB1@159 -46.15 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 01:59:31

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB160@0 -47.05 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:00:50

30MHz_15kHz_2674.995MHz_DFT-s-OFDM QPSK_RB160@0 -37.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:01:37


30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB1@0 -37.53 dBm




30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB1@0 -47.37 dBm




30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB1@77 -37.40 dBm




30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB1@77 -46.87 dBm




30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB75@0 -46.64 dBm



30MHz_30kHz_2511MHz_DFT-s-OFDM QPSK_RB75@0 -37.14 dBm




30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:39:35

30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:38:48

30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@77 -47.01 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:40:08

30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@77 -37.38 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:40:55

30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB75@0 -47.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:41:29

30MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB75@0 -37.19 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:42:15

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB1@0 -46.95 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:25:37

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB1@0 -36.84 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:26:22

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB1@77 -37.58 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:27:35

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB1@77 -46.94 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:26:51

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB75@0 -36.70 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:50:05

30MHz_30kHz_2674.98MHz_DFT-s-OFDM QPSK_RB75@0 -47.42 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:49:18

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@0 -37.46 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:03:38

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@0 -46.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:02:51

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@215 -46.94 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:04:11

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@215 -37.67 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:04:57

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB216@0 -36.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:06:17

40MHz_15kHz_2516.01MHz_DFT-s-OFDM QPSK_RB216@0 -47.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:05:30

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -37.18 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:03:48

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -47.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:03:04

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@215 -37.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:05:28

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@215 -47.85 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:04:43

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB216@0 -36.82 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:15:50

40MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB216@0 -47.33 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:15:03


40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB1@0 -46.49 dBm




40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB1@0 -37.76 dBm




40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB1@215 -37.31 dBm




40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB1@215 -46.76 dBm




40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB216@0 -37.39 dBm



40MHz_15kHz_2670MHz_DFT-s-OFDM QPSK_RB216@0 -46.46 dBm




40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@0 -37.12 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:52:08

40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@0 -47.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:51:21

40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@105 -37.35 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:53:29

40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB1@105 -46.97 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:52:42

40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB100@0 -47.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:54:02

40MHz_30kHz_2516.01MHz_DFT-s-OFDM QPSK_RB100@0 -36.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:54:49

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:29:26

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 19:28:42

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@105 -47.43 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:58:46

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@105 -37.67 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 03:59:33

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB100@0 -46.92 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:00:07

40MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB100@0 -37.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:00:54

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB1@0 -37.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:03:14

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB1@0 -46.50 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:02:27

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB1@105 -46.98 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:03:46

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB1@105 -36.81 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:04:40

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB100@0 -37.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:06:22

40MHz_30kHz_2670MHz_DFT-s-OFDM QPSK_RB100@0 -47.51 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:05:30

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB1@0 -37.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:22:46

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB1@0 -45.67 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:21:59

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB1@269 -36.54 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:24:06

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB1@269 -45.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:23:19

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB270@0 -37.13 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:25:25

50MHz_15kHz_2521.005MHz_DFT-s-OFDM QPSK_RB270@0 -47.32 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:24:38

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -37.16 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:27:41

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@0 -45.93 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:26:54

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@269 -37.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:29:00

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB1@269 -47.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:28:13

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB270@0 -47.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:29:33

50MHz_15kHz_2593.005MHz_DFT-s-OFDM QPSK_RB270@0 -37.40 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:30:20

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.60 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:33:04

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:33:51

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@269 -47.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:34:24

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@269 -37.64 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:35:11

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB270@0 -47.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:35:43

50MHz_15kHz_2664.99MHz_DFT-s-OFDM QPSK_RB270@0 -36.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 02:36:31

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB1@0 -37.56 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:08:23

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB1@0 -47.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:07:36

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB1@132 -36.80 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:09:43

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB1@132 -47.02 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:08:56

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB128@0 -37.48 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:11:03

50MHz_30kHz_2521.02MHz_DFT-s-OFDM QPSK_RB128@0 -47.16 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:10:16

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.29 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:12:18

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.28 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:13:05

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@132 -47.16 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:13:38

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@132 -37.25 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:14:25

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB128@0 -47.39 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:14:59

50MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB128@0 -37.22 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:15:46

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.09 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:17:29

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.45 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:18:16

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@132 -36.96 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:19:36

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB1@132 -46.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:18:49

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB128@0 -37.08 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:20:57

50MHz_30kHz_2664.99MHz_DFT-s-OFDM QPSK_RB128@0 -47.31 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:20:10

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB1@0 -47.00 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:22:11

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB1@0 -37.30 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:22:58

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB1@161 -47.51 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:23:32

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB1@161 -37.49 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:24:19

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB162@0 -36.94 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:25:40

60MHz_30kHz_2526MHz_DFT-s-OFDM QPSK_RB162@0 -46.86 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:24:53

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -37.57 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:27:41

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@0 -47.06 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:26:54

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@161 -47.03 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:28:14

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB1@161 -37.20 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:29:01

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB162@0 -37.24 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:30:22

60MHz_30kHz_2592.99MHz_DFT-s-OFDM QPSK_RB162@0 -45.75 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:29:35

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB1@0 -37.11 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:32:23

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB1@0 -47.89 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:31:36

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB1@161 -37.52 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:33:43

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB1@161 -47.07 dBm




ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:32:56

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB162@0 -47.32 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:34:16

60MHz_30kHz_2659.98MHz_DFT-s-OFDM QPSK_RB162@0 -37.58 dBm



ProjectNo.:2401S73382E Tester:Jim Cheng
Date: 18.MAY.2024 04:35:03