


Intertek Report No.: 231204042SZN-005_Appendix C



Band41-5MHz-16QAM-40620-25RB#0




Intertek Report No.: 231204042SZN-005_Appendix C




Band41-10MHz-QPSK-40620-50RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Band41-10MHz-QPSK-41540-50RB#0




Band41-10MHz-16QAM-39700-50RB#0




Band41-10MHz-16QAM-40620-50RB#0




Intertek Report No.: 231204042SZN-005_Appendix C






Band41-15MHz-QPSK-39725-75RB#0




Band41-15MHz-QPSK-40620-75RB#0




Intertek Report No.: 231204042SZN-005_Appendix C






Band41-15MHz-16QAM-39725-75RB#0




Band41-15MHz-16QAM-40620-75RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Band41-15MHz-16QAM-41515-75RB#0




Band41-20MHz-QPSK-39750-100RB#0




Band41-20MHz-QPSK-40620-100RB#0




Intertek Report No.: 231204042SZN-005_Appendix C






Band41-20MHz-16QAM-39750-100RB#0




Band41-20MHz-16QAM-40620-100RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Band41-20MHz-16QAM-41490-100RB#0




Band66-1.4MHz-QPSK-131979-6RB#0




Band66-1.4MHz-QPSK-132322-6RB#0




Intertek Report No.: 231204042SZN-005_Appendix C



Band66-1.4MHz-QPSK-132665-6RB#0




Band66-1.4MHz-16QAM-131979-6RB#0



Band66-1.4MHz-16QAM-132322-6RB#0



Intertek Report No.: 231204042SZN-005_Appendix C



Band66-3MHz-QPSK-132322-15RB#0

Go To Local Show Remote Screen