

Test Setup Photos




Figure 1 – Radiated Emissions Test Setup, 30MHz – 1GHz

Note: Since the EUT would drain the battery very quickly when transmitting continuously, it was tested with a thin wire run from a DC power supply to the battery input terminals for testing. Some additional preview scan measurements were performed to ensure the additional DC supply wire did not affect the test results. It was found to have no significant effect.

Test Setup Photos




Figure 2 - Radiated Emissions Test Setup, 1 – 19 GHz

Test Setup Photos




Figure 3 - X-axis

Test Setup Photos



Figure 4 - Y -axis

Test Setup Photos



Figure 5 - Z-axis