

Report No.: EED32Q80530301 Page 46 of 56

7 PHOTOGRAPHS OF TEST SETUP



Radiated spurious emission Test Setup-1 (Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)














Report No.: EED32Q80530301







Radiated spurious emission Test Setup-3(Above 1GHz)
There are absorbing materials under the ground.











































