

Report No.: EED32N80682001



PHOTOGRAPHS OF TEST SETUP

Test model No.:DBScar VII

Diagnostic board 1:




Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)



Report No.: EED32N80682001



Diagnostic board 2:



Radiated spurious emission Test Setup-1(Below 1GHz)



Radiated spurious emission Test Setup-2(Above 1GHz)














Report No.: EED32N80682001





Page 39 of 63





Radiated spurious emission Test Setup-5(Above 1GHz)
There are absorbing materials under the ground.





















































