


17 TEST SETUP PHOTOGRAPHS

Picture 1: test set-up for conducted measurements from antenna port




Picture 2: AC-power line conducted emissions test setup

Test results are valid for the tested unit only.

This report shall not be reproduced except in full

NATLABS Oy
P.O. Box 677
FIN-05801 HyvinkääBusiness ID-code
FI 18714394Tel: +358 20 475 2600
Fax: +358 20 475 2719Koneenkatu 12 K17, FIN-05830 Hyvinkää
www.etteplan.come-mail: firstname.lastname@ette.com
www.natlabs.fi



Picture 3: Radiated spurious emission measurement set-up for below 3 GHz measurements, EUT in vertical (V) orientation



Picture 4: Radiated spurious emission measurement set-up for above 3 GHz measurements, EUT in vertical (V) orientation

Test results are valid for the tested unit only.

This report shall not be reproduced except in full

NATLABS Oy
P.O. Box 677
FIN-05801 Hyvinkää

Business ID-code
FI 18714394

Tel: +358 20 475 2600
Fax: +358 20 475 2719

Koneenkatu 12 K17, FIN-05830 Hyvinkää
www.etteplan.com

e-mail: firstname.lastname@ette.com
www.natlabs.fi



Picture 5: EUT in vertical (V) orientation



Picture 6: EUT in horizontal (H) orientation



Picture 7: EUT in horizontal 2 (H2) orientation

Test results are valid for the tested unit only.

This report shall not be reproduced except in full

NATLABS Oy
P.O. Box 677
FIN-05801 HyvinkääBusiness ID-code
FI 18714394Tel: +358 20 475 2600
Fax: +358 20 475 2719Koneenkatu 12 K17, FIN-05830 Hyvinkää
www.etteplan.come-mail: firstname.lastname@ette.com
www.natlabs.fi