



Report No.: EED32P80824602

APPENDIX 1 PHOTOGRAPHS OF TEST SETUP



Radiated emission Test Setup-1 (30MHz~1GHz)



Radiated emission Test Setup-2 (30MHz~1GHz) close up photo












Page 30 of 41




Report No.: EED32P80824602





Radiated spurious emission Test Setup-3(Above 1GHz)



Radiated spurious emission Test Setup-4(Above 1GHz) There are absorbing materials under the ground.









